

Paint Creek Trail Bridge 33.7 Renovation – TF16-0008

Photos of Bridge needing Replacement



**Top of bridge.
Taken from the north side, looking south.**



**Bridge 33.7
Taken from the west side, looking east.**



**Close-up of the middle timber piles
Taken from the west side, looking east**



**Close-up of the northern two support piles
Taken from the west side, looking east**



**Close-up of the 3rd support piles and erosion
Taken from the north side, looking south**



**Close-up of the 3rd, 4th, and 5th support piles
Taken from the Northwest side looking southeast**



Bridge 33.7 – Span over Paint Creek. Taken from the west looking east